TDD Number: 13-08-0020 Photographed by: Carl Overpeck



Photo 1 736 East 3rd Avenue North & South Duplexes.

Direction: Northeast Date: 2/24/14 Time: 12:50



Photo 2 Ductwork in crawl space.

Direction: North Date: 2/22/14 Time: 12:17

TDD Number: 13-08-0020 Photographed by: Carl Overpeck



Photo 3 Ductwork in crawl space.

Direction: Northeast Date: 2/22/14 Time: 12:17



Photo 4 Ductwork in crawl space.

Direction: East Date: 2/22/14 Time: 12:17

TDD Number: 13-08-0020 Photographed by: Carl Overpeck



Photo 5 Crawl space.

Direction: East Date: 2/22/14 Time: 12:17



Photo 6 Crawl space liner.

Direction: East/Down Date: 2/22/14 Time: 12:17

TDD Number: 13-08-0020 Photographed by: Carl Overpeck



Photo 7 Exposed gravel beneath crawl space liner.

Direction: Northeast Date: 2/22/14 Time: 12:18



Photo 8 North room looking into work shop shelves.

Direction: South Date: 2/22/14 Time: 12:19

TDD Number: 13-08-0020 Photographed by: Carl Overpeck




Photo 9 Sewer pipe penetrating slab with exposed gravel.

Direction: Down Date: 2/22/14 Time: 12:19



Photo 10 Pipe runs between north room and work shop.

Direction: Down Date: 2/22/14 Time: 12:19

TDD Number: 13-08-0020 Photographed by: Carl Overpeck



Photo 11 Lined west wall.

Direction: Northwest Date: 2/22/14 Time: 12:21

(b) (6)

Photo 12 Lined west wall in work shop.

Direction: Southwest Date: 2/22/14 Time: 12:21

TDD Number: 13-08-0020 Photographed by: Carl Overpeck




Photo 13 Structural post in crawl space near stairwell.

Direction: Southeast Date: 2/22/14 Time: 12:23



Photo 14 Forced air furnace.

Direction: Northeast Date: 2/22/14 Time: 12:24

TDD Number: 13-08-0020 Photographed by: Carl Overpeck



Photo 15 Liner on wall.

Direction: Northwest Date: 2/22/14 Time: 12:27



Photo 16 Crawl space.

Direction: Northeast Date: 2/22/14 Time: 12:27

TDD Number: 13-08-0020 Photographed by: Carl Overpeck



Photo 17 Detergents etc. in laundry room.

Direction: Northwest Date: 2/22/14 Time: 12:28

TDD Number: 13-08-0020 Photographed by: Carl Overpeck



Photo 18 Floor patch between north room and work shop.

Direction: Down Date: 2/22/14 Time: 12:28

TDD Number: 13-08-0020 Photographed by: Carl Overpeck

Photo 19 Work shop.

Direction: Northeast Date: 2/22/14 Time: 12:28



Photo 20 736 East 3rd Avenue North Duplex.

Direction: Northeast Date: 2/22/14 Time: 12:31